



- Size, shape, position and appearance can vary during continuous production.
- Product consistency can change as process conditions drift.
- Periodic inspection may identify problems only after product has already been produced.

SEE IT BEFORE IT COSTS YOU

FOOD PRODUCTION PROBLEMS WE HELP SOLVE

Continuously monitor characteristics that otherwise rely on periodic checks.

Machine Vision System – Operator Screen

PASS

VALUE		TOLERANCE	STATUS
OD	0.487"	±0.010	●
CPF	47.7	±0.5	●
Length	125.0 ft	±1.0	●
Speed	600 ft/min	±10	●

Holds

Alarms



Scan the QR code to view CORPEX
products & solutions for machine vision systems.
www.corpex.biz | 416.358.0005