



Finished diameter is only part of the picture. Changes in winding pitch, spacing, surface condition and other measurable characteristics can develop during production and may not be caught until the next quality check.

- 

Small variations can become costly production problems.

CORPEX machine vision systems continuously monitor critical points in your process, detecting measurable changes and deviations as they happen, so your team can take action sooner.

Monitor measurable changes throughout production.

www.corpex.biz | 416.358.0005